

**Sent Date:**

## Pit Status Evaluation:

### Pit Status Review Documents:

- |  |                  |
|--|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 583118   | Date: 12/05/1978 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 309546  | Date: 8/13/1992  |
| Doc #: 309584  | Date: 3/26/1993  |
| Doc #: 896114  | Date: 09/05/2000 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #:   | Date:            |
| <input type="checkbox"/> COGIS Document – Doc #:   | Date:            |
| <input type="checkbox"/> Pit Inventory – Doc #:  | Date:            |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #:  |                  |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached)  |                  |
| <input checked="" type="checkbox"/> Other: Doc #1082875, 6/15/2000 - Correspondence documenting that sampling was preformed in former pit area - sample results not found. |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Well originally plugged 12/4/1992(?), replugged 7/13/2000; passed final inspection 9/5/2000. Inspections document pit was backfilled between 1992 and 1993.

#### Pit Status Review Summary:

Records document an unlined earthen produced water pit on location. Pit was backfilled between 8/13/1992 and 3/26/1993 inspections. Well was plugged and passed final reclamation inspection 9/5/2000; location is now a housing development. Pit status has been changed to closed.