

**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 1. Overview of newest portion of location.**



**Photo 2. Stained soil from hose drag.**

**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 3. Close up of hose drag soil staining.**



**Photo 4. Example of stained soil on location.**

Inspection Photos  
Location Name: Surprise Central Facility  
Location ID: 436676



Photo 5. No capacity on tank label.



Photo 6. Free product on stormwater in metal berm.



**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 7. Dead bird inside metal berm.**



**Photo 8. Close up of bird from photo 7, surrounded by oily debris.**

**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 9. Dead bird outside metal berm.**



**Photo 10. Close up of bird from photo 9.**

**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 11. Stained soil and bucket of oily waste.**



**Photo 12. Close up of oily waste bucket from photo 11.**