

**Inspection Photos**  
**Location Name: Refuge 0780 S16**  
**Location ID: 451456**



**Photo 1. Containment parts becoming debris, unused equipment on location.**



**Photo 2. Equipment stored on location.**



**Inspection Photos**  
**Location Name: Refuge 0780 S16**  
**Location ID: 451456**



**Photo 3. Example of stained soil on location.**



**Photo 4. Site degradation – rutting.**