

Inspection Photos
Location Name: Vetting 15-H
Location ID: 322888



Photo 1 – Location



Photo 2 – Generator not grounded, Crew working on getting it grounded today.

Inspection Photos
Location Name: Vetting 15-H
Location ID: 322888



Photo 3 – Chemical not in secondary containment, crew working on getting containment and covered