

Inspection Photos

Loc#449274

Operator: Sandridge

Inspection Number: 692401135

Inspection Date: 6/26/19





Photo#1:
Overview of Location to Northwest.

June 26, 2019



Photo#2:
NW Corner of site, repaired, where washout occurred.



Photo#3:
Sediment deposit that occurred when corner washed out.

June 26, 2019



Photo#4:
Weir installation at SW corner, looking out to perimeter.

June 26, 2019



Photo#5:
Weir installation at SW corner, looking into pad.



Photo#6:
View along East berm; emerging vegetation and
Canada thistle.



Photo#7:
View along East berm; emerging vegetation and
Canada thistle.

June 26, 2019



Photo#8:
Lack of BMPs along both sides of access road.



Photo#9:
Lack of BMPs along access road at culvert.

June 26, 2019