

Inspection Photos

Loc#324752

Operator: Sandridge

Inspection Number: 692401134

Inspection Date: 6/26/19





Photo#1:

Aerial view of Location. Two Interim Reclamation areas are identified as well as BMP area of concern shown in Photos #s 6 & 7.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#2:
Showing results of lack of BMPs on Access Road.



Photo#3:
Showing results of lack of BMPs on Access Road.

June 26, 2019



Photo#4:
Showing results of lack of BMPs on Access Road.

June 26, 2019



Photo#5:
Showing results of lack of BMPs on Access Road.
Insert is of unknown infrastructure run over by off road traffic.



Photo#6:
BMP area of concern & Area #2 (aerial) 5/7/19.



Photo#7:
BMP area of concern & Area #2 (aerial) 6/26/19.

June 26, 2019



Photo#8:
View of Area #1 (aerial) 5/7/19.



Photo#8:
View of Area #1 (aerial) 6/26/19. Note Debris in
Insert.

June 26, 2019



Photo#10:
Stockpiles have no BMPs. Inserts 5/7/19.



Photo#11:
Stockpiles have no BMP; one pushed off
Location. Inserts 5/7/19.

June 26, 2019