

Inspection photos D31 Pad Location # 335674



No additional signage found.

No additional signage found.

Inspection photos
D31 Pad
Location # 335674



EF12B-DX API # 05-045-15486



Gas bubbling in cellar.

Inspection photos
D31 Pad
Location # 335674



EF12C API # 05-045-14659



Gas bubbling in cellar.

Inspection photos
D31 Pad
Location # 335674



Open hole back filled.



Some settling of hole.