

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #1 – Facility sign.



Photo #2 – View of open excavation, soil stockpiles, and associated equipment located at SE corner of pad.



Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #3 – View into excavation from north side.



Photo #4 – Flowline equipment daylighting inside of excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #5 – Soil stockpile west of excavation.



Photo #6 – Produced Water tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #7 – NP EF01C 34 P27 595 well sign.



Photo #8 - NP EF01C 34 P27 595 wellhead with oil-stained material.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #9 - NP EF01B 34 P27 595 well sign.



Photo #10 - NP EF01B 34 P27 595 wellhead with oil-stained material.

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #11 - NP EF09F-27 P27 595 well sign.



Photo #12 - NP EF09F-27 P27 595 wellhead with oil-stained material.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N. Parachute EF P27 595 Pad & P27 Flowline Release

Location ID: #335806 & Spill/Release ID: #464855

Inspection Date: June 20, 2019



Photo #13 - NP EF01E-34 P27 595 well sign.



Photo #14 - NP EF01E-34 P27 595 wellhead with oil-stained material.