

# *Inspection Photos*

*Loc#324757*

*Operator: Sandridge*

*Inspection Number: 692401140*

*Inspection Date: 6/27/19*





Photo#1:  
Overviews of Location to Northwest.

June 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Mutual Loc#324757



Photo#2:  
View of stockpile bermed at NE portion of Location,  
being utilized for construction work on site



Photo#3:  
View from top of stockpile to Northwest.

June 27, 2019



Photo#4:  
Heavy infestation of Canada thistle on East side of stockpile. .



Photo#5:  
East side of stockpile inundated by irrigation water.

June 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Mutual Loc#324757



Photo#6:  
Soil is being utilized for construction.



Photo#7:  
Soil is being utilized for construction.

June 27, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Mutual Loc#324757



**Photo#8:**  
Noxious Weeds, Canada thistle and White top are established on Location.



**Photo#9:**  
Noxious Weeds, Canada thistle and White top are established on Location.

June 27, 2019