

Final Reclamation Inspection

July 1, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 323427

Inspection Document #: 697500277

Weld County, CO

NWNE Section 21 T4N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CPC-ULRICH #21-1
Location ID: 323427



Photo 1. Photo taken from the tank battery location, facing North. Tank battery location is not reflective or reference crop areas as no crop growth was observed.

Inspection Photos
Location Name: CPC-ULRICH #21-1
Location ID: 323427



Photo 2. Photo taken from the tank battery location, facing South. See comments under Photo 1. Photo also illustrates the access road has not been reclaimed.