

Final Reclamation Inspection

July 1, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 449022

Inspection Document #: 697500285

Weld County, CO

NWSW Section 26 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Loloff B /26-33 Tank
Battery
Location ID: 449022



Photo 1. Photo taken from the southern tank battery, facing West. Operator has failed to perform Final Reclamation activities (i.e., gravel remains, location has not been contoured, etc.).

Inspection Photos
Location Name: Loloff B /26-33 Tank
Battery
Location ID: 449022



Photo 2. Photo taken from the southern tank battery, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Loloff B /26-33 Tank
Battery
Location ID: 449022



Photo 3. Photo taken from the southern tank battery, facing East. See comments under Photo 1.