

## Inspection Photos

Location Name: LORENCITO 11-30-34-66 TR

API#: 05-071-08770

INSP. #: 695100986



PHOTO 1: WELLHEAD




PHOTO 2: WELL SIGN

## Inspection Photos

Location Name: LORENCITO 11-30-34-66 TR

API#: 05-071-08770

INSP. #: 695100986



Colorado Oil & Gas Conservation Commission  
37.05504, -104.82353, 2251.0m, 76°  
2019/07/08 14:41:19

**PHOTO 3: UNUSED EQUIPMENT STORED ON SOUTHEAST  
CORNER OF LOCATION. REMOVE UNUSED EQUIPMENT  
COMPLY WITH RULE 603.f. CA DATE 8/8/19**



Colorado Oil & Gas Conservation Commission  
37.05503, -104.82354, 2251.0m, 74°  
2019/07/08 14:41:35

**PHOTO 4: UNUSED EQUIPMENT STORED ON SOUTHEAST  
CORNER OF LOCATION. REMOVE UNUSED EQUIPMENT  
COMPLY WITH RULE 603.f. CA DATE 8/8/19**