FIR RESOLUTION FORM

Overall Status: <u>CAC</u>

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

   1 CA Completed
   0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON   State: TX   Zip: 77070

Contact Name and Telephone:

Name:

Phone: ( )   Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

  FIR Document Number: 674302048

  Inspection Date: 05/13/2019   FIR Submit Date: 05/13/2019   FIR Status:

Inspected Operator Information:

  Company Name: NOBLE ENERGY INC   Company Number: 100322

  Address: 1001 NOBLE ENERGY WAY

  City: HOUSTON   State: TX   Zip: 77070

LOCATION - Location ID: 310776

  Location Name: KISSLER K-64N66W   Number: 21SESW   County:

  Qtrqtr: SESW   Sec: 21   Twp: 4N   Range: 66W   Meridian: 6

  Latitude: 40.293350   Longitude: -104.786776

FACILITY - API Number: 05-123-   -00   Facility ID: 310776

  Facility Name: KISSLER K-64N66W   Number: 21SESW

  Qtrqtr: SESW   Sec: 21   Twp: 4N   Range: 66W   Meridian: 6

  Latitude: 40.293350   Longitude: -104.786776

`CORRECTIVE ACTIIONS:

1   CA# 125085

Corrective Action: Comply with Rule 603.f .   Date: 05/28/2019

Response: CA COMPLETED   Date of Completion: 05/16/2019

Operator Comment: The broken concrete next to the separators and crude oil tank berm has been cleaned up.

COGCC Decision:

COGCC Representative:	

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed:

Title: EHS Specialist

Date: 7/9/2019 1:15:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files