

Pit Status Evaluation Form

Pit Overview:

Pit Name: BRAMMING	Facility ID: 114324
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: COORS ENERGY COMPANY	
Updated Operator:	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: API # 05-001-06692 (Facility ID 201289), Location 375693	

County: Adams			
Township: 1S	Range: 67W	Section: 31	QQ: CNE
Original Latitude/ Longitude: 39.924829 / -104.926522			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664585 | Date: 2/8/1989 |
| | Doc #: 321494 | Date: 1/4/1990 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 9/21/1989, passed final inspection 1/4/1990

Pit Status Review Summary:

Based on records review, there is no evidence that there was a produced water pit on location. Well was plugged and passed final reclamation inspection 1/4/1990; location is now a housing development. Pit status has been changed to Closed.