

Inspection Photos
Location Name: SCHANK-65N66W /35SWNE
Location #: 323018



Photo #1
Schank #1 (05-123-12444) Wellsite
Temporarily Abandoned | TA
prior insp.



Photo #2
Schank #1 (05-123-12444) Wellsite
Plugged & Abandoned | PA
≈ 15 yds.

Inspection Photos
Location Name: SCHANK-65N66W /35SWNE
Location #: 323018



Photo #3
Schank #1, J 35-2 Battery site

Abandoned

Unused Equipment

*Gas meter run, line pipe, automation controls
prior insp.*



Photo #4
Schank #1, J 35-2 Battery site

Abandoned

Unused Equipment

Line pipe, automation controls - Removed

Gas meter run - Remains