

Inspection Photos
Location Name: LORENCITO 5-30-34-66
API#: 05-071-07011
INSP. #: 695100991



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: LORENCITO 5-30-34-66

API#: 05-071-07011

INSP. #: 695100991



PHOTO 3: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. Ca date 7/24/19