

Inspection Photos
Location #334608
API #045-09481



1 location



2 Location

**Inspection Photos
Location #334608
API #045-09481**



3 Valve on tank # 1 leaking



4 At time of inspection I observed a leak from the load out line on tank #1 inside the tank battery