

Inspection Photos
Location Name: Schmerge Tank Battery
Location ID: 305556



Photo 1: Centralized Tank Battery



Photo 2: Erosion to location.

Inspection Photos
Location Name: Schmerge Tank Battery
Location ID: 305556



Photo 3: Erosion to access road