

Inspection Photos

API: 05-009-06162

Operator: SOVEREIGN OPERATING

Inspection Date: 7/9/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 1. Facing west at the location. Crop has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 2. Facing south at the location. Crop has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 3. Facing east at the location. Crop has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 4. Facing north at the location. Crop has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 5. Facing toward tank battery site near the county road. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 6. Facing toward tank battery site near the county road. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019

Inspection Photos



Photo 7. A plastic pipe remains at tank battery site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06162 | Date: 7/9/2019