

Inspection Photos

API: 05-009-06551

Operator: LORENTZ OIL & GAS

Inspection Date: 7/9/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019

Inspection Photos



Photo 1. Facing east along the former access road. Crop has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019

Inspection Photos



Photo 2. Facing northeast toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019

Inspection Photos



Photo 3. Facing west at the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019

Inspection Photos



Photo 4. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019

Inspection Photos



Photo 5. Facing southwest at the surrounding undisturbed crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06551 | Date: 7/9/2019