

Inspection Photos

Loc#451456

Operator: Sandridge

Inspection Number: 692401141

Inspection Date: 6/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

June 26, 2019



Photo#2:
Looking over Weir into Location.



Photo#3:
Looking out over Weir at discharge area.

June 26, 2019



Inspection Photos: Sandridge Surprise Refuge Loc#451456



Photo#4:
Lack of BMPs at entries.



Photo#5:
Lack of BMPs at entries.

June 26, 2019



Photo#6:
Breach of berm on West side.



Photo#7:
View along East berm.

June 26, 2019



Photo#8:

Carcasses disposed of at Northwest corner of site; also where sediment is transporting onto site.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Refuge Loc#451456



Photo#9:
Lack of BMPs along access road.



Photo#10:
Lack of BMPs along access road..

June 26, 2019