

# *Inspection Photos*

*Loc#413754*

*Operator: Sandridge*

*Inspection Number: 692401142*

*Inspection Date: 6/26/19*





Photo#1:  
Overview of Location to Northwest.

June 26, 2019



Photo#2:  
Heavy ruderal Weed growth on berms and slopes.



Photo#3:  
Canada thistle, Noxious Weed established on site

June 26, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754



Photo#4:  
Wattles that have become Debris.

June 26, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754