

Inspection Photos

07/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313671

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313671



Photo 1: Photo taken from the location, facing west. Photo shows weedy vegetative growth has established/accumulated around the well and production equipment; This is considered a fire hazard and needs to be removed.



Photo 2: Photo shows sign has been updated. Photo also shows weedy vegetative growth has established/accumulated around the well and production equipment.



Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313671



Photo 3: Photo taken from area of the well. Photo shows Canada thistle remains on the location.



Photo 4: Continued from photo 3.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313671



Photo 5: Photo taken from the area of the well. Photo shows Musk thistle (*Carduus nutans*) on the location.



Photo 6: See comments under photo 1.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313671



Photo 7: Photo taken from the southern end of the location, facing southwest. Photo shows Canada thistle on location.



Photo 8: Photo taken from the eastern end of the location, facing southwest. Photo shows Canada thistle (rosettes) on location.