

# Inspection Photos

07/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 454195

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 1:** Photo of meter runs on the west end of the location. Gas freely venting from the meter.



Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 2:** Photo taken from the meter runs on the west end of the location, facing northwest. Photo shows stained soils at the meters and adjacent lands

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 3:** Photo taken from the meter runs on the west end of the location, facing west. Photo shows stained soils at the meters and adjacent lands

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 4:** Photo taken from the meter runs on the west end of the location, facing southwest. Photo shows stained soils at the meters and adjacent lands

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 5:** Photo taken from the meter runs on the west end of the location, facing west. Photo shows stained soils at the meters and adjacent lands

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 6:** Photo taken from the meter runs on the west end of the location, facing west. Photo shows stained soils at the meters and adjacent lands

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 7:** Photo of stained soils west of meters

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 454195



**Photo 8:** Photo taken from the north of the meter runs on the west end of the location, facing south. Photo shows stained soils at the meters and adjacent lands.