

Inspection Photos

07/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313755

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313755



Photo 1: Photo taken from the south of the location, facing north. Photo shows access road (yellow) has not been recontoured/regraded to that of the adjacent lands (blue), or reclaimed.



Photo 2: Photo taken from the location, facing south. Photo shows access road remains has not been reclaimed.

Inspection Photos

Operator Name: PCR OPERATING LLC - 10657

Location ID: 313755



Photo 3: Photo taken from the well location, facing east. Photo shows well location remains predominantly bare and exposed soil, or composed of undesirable weedy plant species. Unable to find evidence that reclamation work has been conducted per corrective actions.



Photo 4: Photo taken from the well location. Photo shows location remains predominantly bare and exposed soil, or undesirable weedy plant species.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313755



Photo 5: Photo taken from the well location. Photo shows location remains predominantly bare and exposed soil, or undesirable weedy plant species. Plants observed in photo predominantly Kochia/Russian thistle.



Photo 6: Photo taken from the well location. Photo shows location remains predominantly bare and exposed soil, or undesirable weedy plant species. Plants observed in photo predominantly Kochia/Russian thistle.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 313755



Photo 7: Photo taken from the access road. Photo shows stained soils.



Photo 8: Photo taken from the adjacent reference area. Photo shows vegetation on reference to compare to vegetation on disturbance area.