

Inspection Photos

Location Name: Great Western Raindance Drill Pad

Location ID: 427917



Photo 1: No grounding rod present

