

Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 1: Tank Battery



Photo 2: Battery sign; significant fading of emergency contact number.



Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 3: Unused equipment



Photo 4: Paint chipped

Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 5: Paint chipped



Photo 6: Holes inside berm wall



Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 7: Stained soil; hole inside of berm



Photo 8: Stained soil in separator house.



Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 9: Unused equipment



Photo 10: Unused equipment

Inspection Photos
Location Name: Spade 1-12 Battery
Location ID: 319612



Photo 11: Trash