

Laramie Energy LLC  
API # 05-077-09152  
Inspection # 696600289



Photo #1. Photo at entrance of location.

Photo #2 Photo at entrance of location.



Laramie Energy LLC  
API # 05-077-09152  
Inspection # 696600289



**Photo #3. Photo of tank Battery**



**Photo #4. Photo at Wellheads**



Laramie Energy LLC  
API # 05-077-09152  
Inspection # 696600289



**Photo #5. Photo of cattle panels on ground or stored on location.**



**Photo #6. Photo of cattle panels on ground or stored on location.**



Laramie Energy LLC  
API # 05-077-09152  
Inspection # 696600289



**Photo #7. BMP (berm in need of maintenance on SW side of location. )**



**Photo #8. Erosion is evident along un-stabilized slope at the SW side of location .**