

Inspection Photos

API: 05-071-08369

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/11/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019

Inspection Photos



Photo 1. Facing along the main road. Rock rip/rap has been installed in areas of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019

Inspection Photos



Photo 2. Facing along the access road. Rock rip/rap has been installed in areas of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019

Inspection Photos



Photo 3. Outlet protection has been installed on the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019

Inspection Photos



Photo 4. Vegetation is well established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019

Inspection Photos



Photo 5. Well sign has not been updated with new operator info.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08369 | Date: 7/11/2019