

Caerus Piceance LLC
API # 05-077-10061
Inspection # 696600297



Photo #1. Photo at entrance of location.
No Battery sign posted at entrance or at tank battery

Photo #2 Photo at Separators on location.

Caerus Piceance LLC
API # 05-077-10061
Inspection # 696600297



Photo #3. Photo of tank battery.

Photo #4. Photo of Wellhead.

Tank labels missing or faded on White Chemical tank.