

**Inspection Photos**  
**Location Name: Lion Creek 7-24H**  
**Location ID: 420728**



**Photo 1 – Tank Battery**



**Photo 2 – Pumping Unit**



**Inspection Photos**  
**Location Name: Lion Creek 7-24H**  
**Location ID: 420728**



**Photo 5 – Stained Soil at the Northeast Tank back bottom valve**