

Inspection Photos
Location Name: Lion Creek 6-23H
Location ID: 420727



Photo 1 – Tank Battery



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Lion Creek 6-23H
Location ID: 420727



Photo 3 – Wellhead Sign




Photo 4 – Stained Soil at wellhead



Inspection Photos
Location Name: Lion Creek 6-23H
Location ID: 420727



Photo 5 – Stained Soil at Northwest back bottom valve



Photo 6 – Glycol unit missing bird protector



Inspection Photos
Location Name: Lion Creek 6-23H
Location ID: 420727



Photo 7 – South Loadline bucket missing lid



Photo 8 – North Loadline bucket missing lid

