

Inspection Photos

Loc#445005

Operator: Sandridge

Inspection Number: 692401138

Inspection Date: 6/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Central T Loc#436676



Photo#2:
Silt fence compromised.



Photo#3:
Silt fence compromised.

June 26, 2019



Photo#4:
Large amounts of Sediment moving on site.



Photo#5:
Sediment moving off site.

June 26, 2019



Photo#6:

Slopes/ stockpiles are not stabilized, resulting in erosion, sediment migration and degradation.



Photo#7:

Slopes/soil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.

June 26, 2019



Photo#8:

Weir is not installed in position to function properly.



Photo#9:

View over top of Weir to outside of Location; showing deposit of Sediment off Location and lack of series of BMPs.

June 26, 2019



Photo#10:
Absence of BMPs at entries and along access road.



Photo#11:
Absence of BMPs at entries and along access road.

June 26, 2019