

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 1. Tubing stored outside tank berm. No labels on tanks.



Photo 2. Water seeping through and under berm. No labels on tanks.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 3. Debris at wellhead.



Photo 4. Close up of photo 3, free product and fluid in cellar, debris in/around cellar.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 5. Example of stained soil on location.



Photo 6. Example of stained soil on location.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 7. Trash and debris in battery berm.



Photo 8. Trash and debris in battery berm.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 9. Trash on location.



Photo 10. Close up of the inside of bucket from photo 9.

Inspection Photos
Location Name: Pintail 16
Location ID: 446527



Photo 11. Trash and debris on location.



Photo 12. Example of stained soil and debris on location.