

Interim Reclamation and Stormwater Inspection

July 10, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 465146

Inspection Document #: 697500326

Adams County, CO

NWNW Section 6 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates one of two vehicle tracking device BMPs.



Photo 2. Photo taken from the entrance of location, facing West. Photo illustrates the second vehicle tracking device BMP.

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 3. Photo taken from the southern location, facing East. Photo illustrates a ditch and berm BMP has been installed in conjunction with silt fence. Disturbance areas have been seeded and straw crimped with mulch.



Photo 4. Photo taken from the southeastern location, facing South. Photo illustrates a sediment trap with a stabilized outlet. Embankment berms of sediment trap and adjacent areas have been temporarily stabilized with erosion control blankets.

Note: Operator should consider future maintenance logistics on the sediment trap if the catch basin is filled with riprap.

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 5. Photo taken from the eastern location, facing North. See comments under Photo 3.



Photo 6. Photo taken from the eastern location, facing East. See comments under Photo 4.

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 7. Photo taken from the eastern location, facing North. See comments under Photo 3. Photo also illustrates the topsoil stockpile which has been stabilized with equipment tracking, seeded, and straw crimped with mulch.

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 8. Photo taken from the northwestern location, facing South. See comments under Photo 3.



Photo 9. Photo taken from the western location, facing South. See comments under Photo 3.

Inspection Photos
Location Name: Rio LC Pad
Location ID: 465146



Photo 10. Photo taken from the southwestern location, facing South. See comments under Photo 4.



Photo 11. Photo taken from the entrance of location, facing South. Photo illustrates the culvert has been stabilized along inlet.