

Inspection Photos
Location Name: Hopkins 41C-19 2
Location ID: 317973



Pic 1 chemical barrels on location/no bmp



Pic 2 trash/chemical bucket with no bmp

Inspection Photos
Location Name: Hopkins 41C-19 2
Location ID: 317973



Pic 3

Pic 4 water tank no volume/illegible

Inspection Photos
Location Name: Hopkins 41C-19 2
Location ID: 317973



Pic 5 stained soil/possible leak inside separator house



Pic 6 stained soil/possible leak outside of separator