

Inspection Photos
Location Name: Hopkins 32-19 1-67 1
Location ID: 317960



Pic 1

Pic 2 stained soil

Inspection Photos
Location Name: Hopkins 32-19 1-67 1
Location ID: 317960



Pic 3 stained soil/possible leak at wellhead



Pic 4