

Inspection Photos  
Operator: BP America  
Location/API #: 067-08997  
Date: 7-10-2019



Photo 1. View of the northern project area from the northeastern corner facing westward. Ditch and berm around perimeter.





Photo 2. View of musk thistles (*Carduus nutans*) within the project area.





Photo 3. View of the project reference area in irrigated field facing northward.