

Inspection Photos
Location Name: Hein#4
Location ID: 318292



**Photo 1 Loc pic. Truck and Trailer parked in front of WH.
Camping trailer and BBQ grill with in 75ft of WH.**

Photo 2 Well Head sign not legible.

Inspection Photos
Location Name: Hein#4
Location ID: 318292



Photo 3 Weeds around PU.

Photo 4 Weeds. No BMP in place for stockpile of dirt.

Inspection Photos
Location Name: Hein#4
Location ID: 318292



Photo 5 Weeds on location. Trash: Car, pieces of metal and various trash on location.



Photo 6 Weeds. Trash: tires, trash cans wood.

Inspection Photos
Location Name: Hein#4
Location ID: 318292



Photo 7 Well is shut in at time of inspection.

Photo 8 Breaker box at PU is in the off position.

Inspection Photos
Location Name: Hein#4
Location ID: 318292



Photo 9 Weeds around electric meter and electrical boxes.