

Inspection Photos
Location Name: Federal 01-02
API #: 067-09066



Wellsign

Inspection Photos
Location Name: Federal 01-02
API # : 067-09066



Wellhead and compressor



Sound meter 100' from compressor in direction of complaint

Inspection Photos
Location Name: Federal 01-02
API # : 067-09066



Erosion on west side of location



Rock run-down

Inspection Photos
Location Name: Federal 01-02
API # : 067-09066



Loose unused insulated wire east side of location



Compressor skid catch pan mostly full of oily fluid

Inspection Photos
Location Name: Federal 01-02
API # : 067-09066



Noxious weed on interim rec area



Noxious weed on edge of access road