

Inspection Photos

API: 071-06558

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

I-API: 071-06558 | Date: 7/11/2019

Inspection Photos



Photo 1. Facing north along the main road to the location. Red arrow points to noxious weeds growing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-06558 | Date: 7/11/2019

Inspection Photos



Photo 2. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-06558 | Date: 7/11/2019

Inspection Photos



Photo 3. There were a few noxious weeds growing along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

IAPI: 071-06558 | Date: 7/11/2019