

Inspection Photos
Operator: BP America
Location/API #: 067-08378
Date: 7-11-2019



Photo 1. View of southern project area from the southeastern edge facing westward.



Photo 2. View of the eastern project area from the southeastern edge facing northward.



Photo 3. View of black plastic netting debris that remains within the project area after 2017 corrective action.