

# Final Reclamation Inspection

July 17, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-21351

Inspection Document #: 697500350

Weld County, CO

SWSW Section 17 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ZIMMERMAN #14-17  
API: 05-123-21351



**Photo 1.** Photo taken from the associated tank battery, facing East. This appears to be shared tank battery with Kerr McGee. Operator has failed to remove their meter shed.

Inspection Photos  
Location Name: ZIMMERMAN #14-17  
API: 05-123-21351



**Photo 2.** Photo taken from the associated tank battery, facing South. Operator has failed to control and manage weeds.