

Maralex Resources Inc.  
API # 05-077-08171  
Inspection # 696600341



Photo #1 Photo of Battery sign at wellhead



Photo #2 Photo at location entrance

Maralex Resources Inc.  
API # 05-077-08171  
Inspection # 696600341



**Photo # 3 Photo at access entrance**



Maralex Resources Inc.  
API # 05-077-08171  
Inspection # 696600341



Photo #4 Photo of disconnected gas meter run



Photo #5 Photo of wellhead



Maralex Resources Inc.  
API # 05-077-08171  
Inspection # 696600341



**Photo # 6 unmarked dead man on location at entrance.**



**Photo # 7 Riser at Separator needs marked and Locked out tagged out**



Maralex Resources Inc.  
API # 05-077-08171  
Inspection # 696600341



**Photo # 8 Riser at Gas meter run need marked and Locked out tagged out**



**Photo # 9 Riser at Gas meter run need marked and Locked out tagged out**