

Inspection Photos
Operator Name: Mustang Resources
Location ID: 323785



Wellhead and location information



Gas meter building

Inspection Photos
Operator Name: Mustang Resources
Location ID: 323785



Domestic tap pictured. Yellow poly with tracer wire



2" Domestic tap with pop-off valve

Inspection Photos
Operator Name: Mustang Resources
Location ID: 323785



Pictures inside gas meter building