

# *Inspection Photos*

*Loc#447512*

*Operator: Sandridge*

*Inspection Number: 692401153*

*Inspection Date: 6/27/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from Entry to West.

June 27, 2019



Photo#2:  
Degradation of site at West end.

June 27, 2019



Photo#3:  
Degradation of site at West end.

June 27, 2019



Photo#4:  
Stockpiled soil material on site



Photo#5:  
Stockpiled soil material on site.

June 27, 2019



Photo#6:  
Trash, debris and supplies not properly stored.

June 27, 2019



Photo#7:  
Area of concern at West side of Location.

June 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512 B