

## Inspection Photos

Location Name: Razor 12H Location ID 430096, Spill #460333

Inspection Date: 7/17/2019



**Photo 1 - View of excavation on west side of pad, looking north**



**Photo 2 - View of excavation on west side of pad, looking south**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Razor 12H Location ID 430096, Spill #460333

Inspection Date: 7/17/2019



**Photo 3 – View of excavation at spill area on west side of pad.**



**Photo 4 – Impacted material stored on location pending disposal.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources