

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #1 – June 17, 2016 Google Earth Aerial depicting subject location. Color-coded boxes depict locations of **Former Tank Battery**, **Pit #416339**, and **TPR Well Pad 36A**.

Photo #2 – Facility sign.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #3 – TPR 132-36 well.



Photo #4 – Uncapped, unmarked flowline riser attached to TPR 132-36.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #5 – TPR 112-6 well.



Photo #6 – TPR 143-36 well.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #7 – View of cut slope on **pad**, looking NE.



Photo #8 – View of cut slope on **pad**, looking SE.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #9 – View of **Tepee Park CFF Pit** (Facility ID #416339), looking NW. Note that pit does not have any fencing installed to prevent wildlife access.



Photo #10 – Wood debris in pit excavation.



Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #11 – View of pit excavation, looking southeast.



Photo #12 – Localized accumulation of oil-stained soil north of pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #13 – Junk and trash located SW of Pit Facility ID #416339, looking SE (1).



Photo #14 - Junk and trash located SW of Pit Facility ID #416339, looking west(2).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #15 – View of **Former Tank Battery**, looking north.
Note liner remaining on location.



Photo #16 – Unmarked HDPE surface flowlines leading north
from **Former Tank Battery** area.



Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #17 – North unused horizontal treater/separator in
Former Tank Battery area.



Photo #18 - South unused horizontal treater/separator in
Former Tank Battery area.



Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #19 – Unused equipment in **Former Tank Battery** area.



Photo #20 – Uncapped, unmarked HDPE surface flowline in **Former Tank Battery** area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TPR Well Pad 36A & Tepee Park CFF Pit

Location ID: #334460 & Pit Facility ID: #416339

Inspection Date: July 9, 2019



Photo #21 – Unused equipment (uncapped, unmarked HDPE surface flowlines) in **Former Tank Battery** area.



Photo #22 – Unidentified stockpile in **Former Tank Battery** area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources