

Inspection Photos

Location 081-06614

Inspection Date: 6/18/2019

Ptasynski 1-X

Photos taken by Kris Neidel



Sign on tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location 081-06614
Inspection Date: 6/18/2019
Ptasynski 1-X
Photos taken by Kris Neidel

Ptasynski well



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location 081-06614
Inspection Date: 6/18/2019
Ptasynski 1-X
Photos taken by Kris Neidel



Ptasynski wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location 081-06614
Inspection Date: 6/18/2019
Ptasynski 1-X
Photos taken by Kris Neidel



Ptasynski pumpjack motor; oil soil, leaky motor housing.



Inspection Photos
Location 081-06614
Inspection Date: 6/18/2019
Ptasynski 1-X
Photos taken by Kris Neidel

Area in green is land treatment area. Soil should be t