

Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Wellhead at 081-07006



**Inspection Photos**

**Location: Clark-Millison #1, 081-07006**

**Inspection Date: 6/18/2019**

**Photos taken by Kris Neidel**



**Land Application Site, facility ID 446519 Area**



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Land Application Site, facility ID 446519 Area



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Land Application Site, facility ID 446519 Area



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Land Application Site, facility ID 446519 Area



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Northeast of wellpad, looking Northeast. Valvebox.





Inspection Photos  
Location: Clark-Millison #1, 081-07006  
Inspection Date: 6/18/2019  
Photos taken by Kris Neidel

Northeast of wellpad, looking Northeast



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Abandon compressor shed.



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Capped flowline, is this flowline compliant with the COGCC flowline rules?




Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Abandon compressor shed, Abandon flowlines.



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Abandon shed.





Inspection Photos  
Location: Clark-Millison #1, 081-07006  
Inspection Date: 6/18/2019  
Photos taken by Kris Neidel

Looking north-east



Inspection Photos  
Location: Clark-Millison #1, 081-07006  
Inspection Date: 6/18/2019  
Photos taken by Kris Neidel



Looking north-east



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored tanks



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Unused Equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored tank



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Fluid seeping out of stored tank.



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored equipment



Inspection Photos  
Location: Clark-Millison #1, 081-07006  
Inspection Date: 6/18/2019  
Photos taken by Kris Neidel



Stored equipment and trash



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Secondary containment with remains of a bird inside. The tank is labeled as "ATF".



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Secondary containment with remains of a bird inside. The tank is labeled as "ATF".



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Secondary containment with remains of a bird inside. The tank is labeled as "ATF".



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored drums





Inspection Photos  
Location: Clark-Millison #1, 081-07006  
Inspection Date: 6/18/2019  
Photos taken by Kris Neidel

Stored equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored Equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored Equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored Equipment

Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Stored Equipment



Inspection Photos

Location: Clark-Millison #1, 081-07006

Inspection Date: 6/18/2019

Photos taken by Kris Neidel



Location of land treatment area